



数显杠杆指示表 Digital Test Indicators





## 主要特点:

- ・任意位置清零(ON/O)
- ・公英制转换(mm/in)
- ·测量时,按下M键,进入HOLD状态,屏幕保留此时的测量值
- ・记录连续测量过程中的最大值(MAX)
- ・记录连续测量过程中的最小值(MIN)
- ・记录连续测量过程中的最大值(MAX)与最小值(MIN)之差(**∆=**MAX-MIN)),
- ・用于平面度和同轴度的测量
- ·显示部分可旋转350度,便于读数。

## FEATURES

- Zero-setting at any position (ON/O)
- Metric/Inch conversion at any position (mm/in)
- Press M button, LCD holds the measuring result (M)
- Hold the max reading during measurement (MAX)
- Hold the minimum reading during measurement (MIN)
- Tracing the balance between Max and Min value ( $\Delta$ =MAX-MIN)
- LCD-display can be rotated by up to 350° to guarantee an optimum reading position

货号 NO	测量范围 Measuring Range mm	精度 Accuracy mm
310-101A	±0.5	$\pm 0.03$
310-101B	±0.5	±0.03

163

## 





此款带数据接口 This type with data output

分辨力:0.01mm Resolution:0.01mm

